


## Vrut do dreva TORX hlava polozávit / Chipboard screws double flat head partial thread TORX



d	dk	k	s
3	6	1.50	T 10
3.5	7	1.75	T 15
4	8	2.0	T 20
4.5	9	2.25	T 20
5	10	2.5	T 25
6	12	3.0	T 25